

#### EXECUTIVE SUMMARY

Two 5000-gallon underground storage tanks were removed from Building 32 at Hill AFB on May 19, 1988. One tank contained leaded gasoline and one tank contained diesel fuel. The tanks were in use until 18 days before their removal. The tanks were observed to be in good condition when pulled with no surface corrosion. No evidence of contamination was noted during tank excavation. Environmental soil samples collected from the tank excavation showed values as high as 170 ug/g oil and grease and 81.2 ug/g xylenes. Soil contamination is probably due to overfills and spills. Future investigations will help determine the vertical and lateral extent of contamination. Utah Department of Environmental Quality has assigned this LUST site the identification code EHNG.